

PURAVANKARA



A
PURAVANKARA HOME AT
SPARKLING SPRINGS

Pride of owning something precious

SPARKLING SPRINGS

AT THE PURVA SOUND OF WATER

Construction Updates

August 2025

Dear Esteemed Customer,

Greetings from Puravankara

It gives us immense pleasure to update you through this edition of Puravankara Newsletter and provide you with the latest information about your home in Sparkling Springs. As we move ahead, we at Puravankara sincerely thank you for your continual faith and trust reposed in the brand.

We are happy to inform you that the construction and infrastructure works at the site is progressing well. We thank you for your understanding that is a construction site with extensive debris, heavy vehicular movement, uneven surfaces and hence keeping in mind your safety, visits to this site is restricted. You may seek prior approval and we can accommodate the scheduled visit from your respective banker.

We are grateful for your kind cooperation.
Team Sparkling Springs





Sparkling Springs

Off Bannerghatta Main Rd, Bengaluru



Construction Updates

Overall view

PHASE 2



Villa 03 - The structure has been completed. Block work, plastering, flooring, door and UPVC window installation, and external façade fixing, sanitary fitting installation are also completed. External painting work in progress.

Villa 04 - The structure has been completed. Block work and plastering & flooring work are completed. Internal painting and UPVC window work are in progress.



Villa 05 - The structure has been completed. Block work and plastering & flooring work are completed. Internal painting and UPVC window fixing work are in progress.

Actual site photograph



Villa 06 - The structure has been completed. Block work and plastering, flooring work have been completed. Internal painting work are in progress. External painting has commenced.



Villa 07 - The structure has been completed. Block work and plastering, flooring work have been completed. Putty work are in progress. External painting has commenced.



Villa 08 - Structure is completed. Block work is completed. Plastering completed, flooring work in progress. External paint has commenced.



Villa 09 – Structure is completed. Block work is completed. Plastering completed, flooring work and external paint work in progress.



Villa 10 - The structure has been completed. Block work and plastering have also been completed. Flooring, putty work, UPVC window installation work, and external façade work are in progress.

Villa 11 - The structure has been completed. Block work and plastering have also been completed. Flooring, UPVC work completed, and external façade work completed, external painting work in progress.



Villa 12 – Structure is completed. Block work is completed. Plastering is completed. Flooring, putty, external façade work in progress.

Villa 13 - Structure is completed. Block work is completed. Plastering work is completed & flooring work in progress.



Villa 14 - The structure has been completed. Block work and plastering have also been completed. Flooring, UPVC work completed, and external façade work completed, external painting work in progress.

Villa 15 - Structure is completed. Block work is completed. Plastering work is completed and flooring work & putty work in progress.



Villa 16 - Block work, plastering, flooring, UPVC window fixing is completed. Door fixing, painting & external façade work are completed. Final coat painting working progress.

Villa 17 - Block work, plastering, flooring, door and UPVC window installation, and external façade fixing have been completed. Sanitary fittings and external painting work are also completed.



Villa 18 - Block work & plastering completed. Flooring, UPVC window fixing, painting & external façade work in progress.

Villa 19 - Block work & plastering, flooring, UPVC window & door fixing is completed. Painting & external façade work completed.

Villa 20 - Block work, plastering & flooring completed. UPVC window & door fixing, painting and external façade work completed.

Villa 21 - Block work & plastering, flooring, UPVC window & door fixing is completed. Painting & external façade work completed.

Villa 22 - Block work & plastering, flooring, UPVC window & door fixing is completed. Painting & external façade work completed.



Villa 23 – Structure work is completed. Block work is completed. Plastering work completed, water proofing work completed and flooring work in progress.

Villa 24 - Structure work is completed. Block work is completed. Plastering completed and flooring work and putty work in progress.

Actual site photograph



Villa 25 - Structure work is completed. Block work, plastering, and flooring have been completed. Painting, UPVC window and door fixing, and external façade work are also completed. Hardscape work in progress.

Villa 26 - Structure work is completed. Block work, plastering, and flooring have been completed. Painting, UPVC window and door fixing, and external façade work completed.



Villa 27 - 100% completed.

Villa 28 - Structure work has been completed. Block work, plastering, and flooring have also been completed. Painting, UPVC window fixing, and external façade work are completed.



Villa 29 - Structure work is completed. Block work is completed. Plastering work completed and water proofing work in progress.

Villa 30 - Structure work is completed. Block work is completed. Plastering work completed and water proofing work in progress.



Villa 31 - Blockwork, plastering & flooring & door fixing completed. UPVC window fixing completed & painting work in progress. External façade work completed.

Villa 32 - Blockwork, plastering & flooring & door fixing completed. UPVC window fixing completed & painting work in progress. External façade work completed.

Villa 33 - Blockwork, plastering & flooring & door fixing completed. UPVC window fixing completed & painting work in progress. External façade work completed.

Villa 34 - Blockwork, plastering & flooring & door fixing completed. UPVC window fixing completed & painting work in progress. External façade work completed.

Villa 35 - Block work & plastering is completed. Flooring & painting work is in progress. External façade work in progress.

Actual site photograph



Villa 62 - Block work, plastering, flooring, UPVC window & door fixing is completed. Painting & external façade work completed and external final coat painting work in progress.

Villa 63 - Block work, plastering, flooring, UPVC window & door fixing is completed. Painting & external façade work completed and final coat painting work in progress.

Villa 64 - Block work, plastering, flooring, UPVC window & door fixing is completed. Painting & external façade work completed and final coat painting work in progress.

Villa 65 - Block work, plastering, flooring, UPVC window & door fixing is completed. Painting & external façade work completed and final coat painting work in progress.



Villa 66 - Block work, plastering, flooring, door and UPVC window installation, and external façade fixing have been completed. Sanitary fittings and external painting work are also completed.

Villa 67 - Block work, plastering, flooring, door and UPVC window installation, and external façade fixing have been completed. Sanitary fittings and external painting work are also completed.

Villa 68 - Block work & plastering is completed. Flooring, UPVC window fixing & painting work in progress.

Actual site photograph



Villa 69 - Block work, plastering, and flooring have been completed. Internal painting and UPVC window fixing are also completed. Door fixing, external façade installation completed, and external painting work are in progress.

Villa 70 – The structure has been completed. Block work and plastering are completed. Flooring and painting works are in progress.

Villa 71 – The structure has been completed. Block work and plastering are completed. Flooring and painting works are in progress.

Villa 72 – The structure has been completed. Block work, plastering, and flooring have also been completed. External façade work in progress.



Villa 73 - Block work, plastering, flooring, door and UPVC window installation, and external façade fixing have been completed. Sanitary fittings and external painting work are also completed.

Villa 74 - Block work, plastering, flooring, door and UPVC window installation, and external façade fixing have been completed. Sanitary fittings and external painting work in progress

Villa 75 - Block work, plastering, flooring, door and UPVC window installation, and external façade fixing have been completed. Sanitary fittings and external painting work are also completed.

PHASE 3



Villa 148 - Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work are completed. Sanitary fitting work in progress.

Villa 149 - Structure completed. Block work & plastering work is completed. Flooring work, UPVC window fixing work in progress.

Villa 150 - Structure completed. Block work & plastering work is completed. Flooring work, UPVC window fixing work in progress.



Villa 151 - Structure completed. Block work, plastering, flooring, door and UPVC window installation have been completed. Painting and external façade work are in progress.

Villa 152 - Structure completed. Block work, plastering, flooring, door and UPVC window installation have been completed. Painting and external façade work are in progress.



Villa 153 - Block work, plastering, flooring, and UPVC window installation have been completed. Painting and external façade work are in progress.

Villa 154 - Block work, plastering, flooring, and UPVC window installation have been completed. Painting and external façade work are in progress.

Villa 155 - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed.



Villa 156 - Structure completed. Block work & plastering is completed, flooring & water proofing completed. External painting work in progress.

Villa 157 - Structure completed. Block work & plastering is completed, flooring & water proofing completed. External painting work in progress.

Villa 158 - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed.

Actual site photograph



Villa 159 - Block work, plastering, flooring, door, and UPVC window installation have been completed. Painting work and external façade work are in progress.

Villa 160 - Block work, plastering, flooring, UPVC window installation have been completed. Painting work and external façade work completed.

Villa 161 - Block work & plastering is completed. Flooring, UPVC window & door fixing, painting and external façade work in progress.

Villa 162 - Block work & plastering is completed. Flooring, UPVC window works, painting and external façade work in progress.



Villa 165 - Block work, plastering, flooring, and UPVC window installation have been completed. Painting and external façade work completed.

Villa 164 - Block work, plastering, flooring, and UPVC window installation have been completed. Painting and external façade work completed.

Villa 163 - Block work, plastering & flooring is completed. Painting & UPVC window work fixing & external façade work in progress.

Actual site photograph



Villa 166 - Block work, plastering, flooring, and UPVC window installation have been completed. External façade work is completed and external painting work in progress.

Villa 167 - Block work, plastering, flooring, and UPVC window installation have been completed. Painting and external façade work are in progress.

Villa 168 - Block work and plastering, flooring work are completed. Painting and external façade work are in progress.

Villa 169 - Block work and plastering, flooring work are completed. Painting and external façade work in progress.



Villa 170 - Block work, plastering, and flooring have been completed. UPVC window fixing work also completed. Painting and external façade works are completed.

Villa 171 - Block work & plastering is completed. Flooring, UPVC window fixing, painting work & external façade work in progress.

Villa 172 - Block work, plastering, and flooring have been completed. UPVC window fixing work also completed. Painting and external façade works are completed.

Villa 173 - Block work, plastering and flooring work completed. UPVC window fixing, painting work & external façade work is in progress.

Villa 174 - Block work, plastering and flooring work completed. UPVC window fixing, painting work & external façade work in progress.

Actual site photograph



Villa 175 - Block work and plastering are completed. Flooring, door & UPVC window installation work have also been completed, and external painting, façade work in progress.

Villa 176 - Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed.

Villa 177 - Block work and plastering are completed. Flooring, door & UPVC window installation work have also been completed, and external painting, façade work in progress.



Villa 178 - Block work, plastering and flooring work completed. Window installation and painting work in progress.

Villa 179 - Block work, plastering and flooring work completed. Window installation, door installation and painting work in progress.



Villa 180 - Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed.

Villa 181 - Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed.

Villa 182 - Block work and plastering are completed. Flooring, door & UPVC window installation work have also been completed, and external painting, façade work in progress.



Villa 185 - Block work and plastering are completed. Flooring and UPVC window, door installation work have also been completed, and external façade& painting in progress.

Villa 184 - Block work and plastering are completed. Flooring and UPVC window installation work have also been completed, and external painting in progress.

Villa 183 - Block work and plastering are completed. Flooring and UPVC window installation work have also been completed, and external painting in progress.

Actual site photograph



Villa 186 - The structure has been completed. Block work, plastering, and flooring have been completed. Painting and UPVC window fixing have also been completed, and external painting work in progress.

Villa 187 - The structure has been completed. Block work ,plastering and flooring work have also been completed. UPVC window installation, and painting work in progress.



Villa 188 - Block work, plastering, and flooring have been completed. Painting and UPVC window fixing have also been completed, and external façade completed and external painting work in progress.

Villa 189 - Block work and plastering have been completed. Internal flooring, UPVC window fixing, and external painting work in progress.



Villa 190 - Block work, plastering and flooring work are completed. UPVC window installation work , external façade and painting work in progress.

Villa 191 - Block work and plastering have been completed. Flooring and UPVC window installation work are also completed, external painting work in progress.



Villa 192 - Block work and plastering have been completed. Flooring and UPVC window installation work are also completed. External painting work in progress.

Villa 193 - Block work, plastering & flooring work completed. Painting work, UPVC window & external façade works in progress.

Villa 194 - Block work and plastering have been completed. Flooring and UPVC window installation work are also completed, external painting work in progress.

Villa 195 - Block work, plastering & flooring work completed. Painting work, UPVC window & external façade works in progress.



Villa 196 - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed.

Villa 197 - The structure has been completed. Block work, plastering, flooring, door and UPVC window fixing have been completed. Painting, external façade work, and hardscape work in progress.



Villa 198 - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed.

Villa 199 - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed.



Villa 200 - The structure has been completed. Block work, plastering, flooring, door and UPVC window fixing have been completed. Painting and external façade work are in progress.

Villa 201 - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, painting, external façade work, and sanitary fitting work are also completed.



Villa 202 - The structure has been completed. Block work ,plastering & flooring work are completed. Painting, and UPVC window fixing work in progress.

Villa 203 - The structure has been completed. Block work ,plastering & flooring work are completed. Painting, and UPVC window fixing work in progress.



Villa 204 - The structure has been completed. Block work and plastering are completed. Flooring and internal painting work have also been completed. UPVC window and door fixing work are in progress. External façade work is also in progress.

Villa 205 - The structure has been completed. Block work and plastering are completed. Flooring ,internal painting, UPVC window fixing work have been completed. Door fixing work are in progress. External façade work is also in progress.



Villa 206 - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed.

Villa 207 - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed.

Contact us

Site Office :

Sparkling Springs

South Taluk, Kammanahalli Village , Begur Hobli Road,
Off Bannerghatta Main Rd, Bengaluru, Karnataka – 560076

Regional Office :

Puravankara Limited. #130/1, Ulsoor Road,
Bengaluru - 560 042

Email : crm@puravankara.com (Subject line – Project name/ unit number)

Call Us : +91 - 80-67724001 / 1 860 208 0000

Web : www.puravankara.com

OC Number :

JDBL (S)/ADBL/OC/11/2020-21