

**PURAVANKARA**

Pride of owning something precious

# SPARKLING SPRINGS

AT THE PURVA SOUND OF WATER

## Construction Updates

**FEB 2026**



A  
PURAVANKARA HOME AT  
SPARKLING SPRINGS

<https://www.puravankara.com/>

year Esteemed @ustamer,


*Greetings from Puravankara*

*'It gives me immense pleasure to update you through this edition of Ouravanaha Newsletter and provide you with the latest information about your home in Startling Springs. Please use the link ahead, we at Puravankara sincerely thank you for your continual faith and trust reposed in the brand.*

*We are happy to inform you that the construction and site works of the site is progressing well. We thank you for your understanding that as a construction site there will be some noise, uneven surfaces and fence keeping in mind your safety, we have restricted the site. You may need prior approval and we can accommodate the scheduled visit from your respective dates.*

*We are grateful for your kind cooperation.*

*Thank you for your support.*





# Sparkling Springs

Off Bannerghatta Main Rd, Bengaluru



## Construction Updates

Overall View

**PHASE 2**

## PHASE 2



**Villa 03** - Block work, plastering, flooring, door and UPVC window installation, and external façade fixing, External painting works are completed. sanitary fitting installation are also completed. Hardscape work & Softscape works are Completed

**Villa 04** - Block work, plastering, flooring, door and UPVC window installation, and external façade fixing, External painting work, sanitary fitting installation are also completed. Hardscape work & Softscape Completed.



**Villa 05** - Block work, plastering, flooring, door and UPVC window installation, and external façade fixing, External painting work, sanitary fitting installation are also completed. Hardscape work & Softscape work also Completed.

Actual site photograph



**Villa 06** - The structure has been completed. Block work and plastering, flooring work have been completed. Internal painting work completed, UPVC window installation work completed. External painting work completed & facade work completed . Hardscape and landscape works are completed.



**Villa 07** - The structure has been completed. Block work and plastering, flooring work have been completed. Internal painting work completed, UPVC window installation work completed. External painting work completed & facade work completed . Hardscape and landscape works are completed.

Actual site photograph



**Villa 08** - The structure has been completed. Block work and plastering, flooring work have been completed. Internal painting works are completed. External painting & facade works are completed. Hardscape and landscape work are completed.



**Villa 09** – The structure has been completed. Block work and plastering, flooring work have been completed. Internal painting work completed. CP & sanitary fitting work completed. External painting work completed& facade work completed and hardscape work and Landscape works are completed



**Villa 10** - The structure has been completed. Block work and plastering have also been completed. Flooring, putty work, UPVC window installation work, and external façade work are completed. Hardscape work completed and landscape work completed .External painting work in progress.

**Villa 11** - The structure has been completed. Block work and plastering have also been completed. Flooring, UPVC work completed, and external façade work Completed, external painting work in completed. Hardscape & Landscape works completed.



**Villa 12** – Structure is completed. Block work is completed. Plastering, internal flooring, putty, door installation work completed.UPVC window installation , External façade work completed. Hardscape work completed and landscape work completed

**Villa 13** - Structure is completed. Block work is completed. Plastering work is completed & flooring work, putty, external façade work completed, CP Sanitary fitting work in progress and Hardscape work completed and landscape work completed .



**Villa 14** - The structure has been completed. Block work and plastering have also been completed. Flooring, UPVC work completed, and external façade work Completed, external painting work completed, and sanitary fitting installation Completed. Hardscape work completed and landscape work completed

**Villa 15** - The structure has been completed. Block work and plastering, flooring, Putty and internal painting work completed. Flooring completed, and external façade work and external painting work Completed. Hardscape work completed and landscape work completed



**Villa 16** - Block work, plastering, flooring, UPVC window fixing is completed. Door fixing, Painting & external façade work are Completed. final coat Paintin completed, Hardscape & landscape works are completed

**Villa 17** - Block work, plastering, flooring, door and UPVC window installation, and external façade fixing have been completed. Sanitary fittings and external painting work are also completed. Hardscape & landscape work completed .

Actual site photograph



**Villa 18** - Block work & plastering is completed. Flooring, UPVC window fixing, painting & external façade work Completed. Hardscape and landscape works are completed.

**Villa 19** - Block work & plastering, flooring, UPVC window & door fixing is completed. Painting & external façade work Completed and hardscape & softscape works are Completed.

**Villa 20** - Block work, plastering & flooring is completed. UPVC window & door fixing, painting and external façade work completed and hardscape works are completed.

**Villa 21** - Block work & plastering, flooring, UPVC window & door fixing is completed. Painting & external façade work Completed and hardscape & landscape works are completed.

**Villa 22** - Block work & plastering, flooring, UPVC window & door fixing is completed. Painting & external façade work Completed and hardscape & landscape works are completed.



**Villa 23** - Block work & Plastering work completed, flooring work and putty work completed UPVC window work completed and external façade work & hardscape works are completed.

**Villa 24** - Structure work is completed. Block work is completed. Plastering completed and flooring work and putty work in completed, UPVC window and external façade works are completed. hardscape and landscape works are completed



**Villa 25** - Structure work is completed. Block work, plastering, and flooring have been completed. Painting, UPVC window and door fixing, and external façade work are also completed. Hardscape & landscape works are completed.

Villa 26 - Structure work is completed. Block work, plastering, and flooring have been completed. Painting, UPVC window and door fixing, and external façade work are also completed. Hardscape & landscape works are completed.



**Villa 27** - 100% completed

**Villa 28** - Structure work has been completed. Block work, plastering, and flooring have also been completed. Painting, UPVC window fixing, and external façade work are completed. Hardscape & landscape works are completed.

Actual site photograph



**Villa 29** - Structure work is completed. Block work is completed. Plastering work completed and water proofing work completed and flooring, putty, external façade work completed. Hardscape & landscape works are completed.

**Villa 30** - Structure work is completed. Block work is completed. Plastering work completed external façade work completed, Hardscape & landscape works are completed.

**Villa 31** - Blockwork, Plastering & flooring & door fixing is completed. UPVC window fixing completed & painting work completed. External façade work completed. Hardscape & Landscape works are completed

**Villa 32** - Blockwork, Plastering & flooring & door fixing works completed. UPVC window fixing & painting works are completed. External façade work completed. Hardscape & landscape works are completed.

**Villa 33** - Blockwork, Plastering & flooring & door fixing is completed. UPVC window fixing completed & painting work completed. External façade work completed. Hardscape & Landscape works are completed.

**Villa 34** - Blockwork, Plastering & flooring & door fixing works are completed. UPVC window fixing completed & painting work completed. External façade work completed. Hardscape & landscape works are completed



**Villa 35** - Block work & plastering works are completed. Flooring & painting works are completed. External façade work Completed. Hardscape and landscape works are completed.

Actual site photograph



**Villa 62** - Block work, plastering, Flooring, UPVC window & door fixing completed. Painting & external façade works completed and external final coat painting work completed. Hardscape & landscape works are completed

**Villa 63** - Block work, plastering, Flooring, UPVC window & door fixing works are completed. Painting & external façade work completed and final coat painting works are completed. Hardscape & landscape works are completed

**Villa 64** - Block work, plastering, Flooring, UPVC window & door fixing is completed. Painting & external façade work completed and final coat painting work completed. Hardscape & landscape works are completed.

**Villa 65** - Block work, plastering, Flooring, UPVC window & door fixing is completed. Painting & external façade work completed and final coat painting work completed. Hardscape & landscape works are completed



**Villa 66** - Block work, plastering, flooring, door and UPVC window installation, and external façade fixing have been completed. Sanitary fittings and external painting work are also completed. Hardscape & landscape works are completed

**Villa 67** - Block work, plastering, flooring, door and UPVC window installation, and external façade fixing have been completed. Sanitary fittings and external painting work are also completed. Hardscape & landscape works are completed.

**Villa 68** - Block work & plastering is completed. Flooring, UPVC window fixing work completed & painting work completed. Hardscape work completed and Landscape work completed.

Actual site photograph



**Villa 69** - Block work, plastering, and flooring have been completed. Internal painting and UPVC window fixing are also completed. Door fixing, external façade installation completed, and external painting work Completed. Hardscape & Landscape works are completed.

**Villa 70** – The structure has been completed. Block work and plastering are completed. Flooring completed and painting works are completed. . Hardscape & Landscape works are completed.

**Villa 71** – The structure has been completed. Block work and plastering are completed. Flooring completed and painting works are completed. . Hardscape & Landscape works are completed.



**Villa 72** – The structure has been completed. Block work, plastering, and flooring have also been completed. painting work completed. . Hardscape & Landscape works are completed.

**Villa 73** - Block work, plastering, flooring, door and UPVC window installation, and external façade fixing have been completed. Sanitary fittings and external painting work are also completed. Hardscape & Landscape works are completed.

**Villa 74** - Block work, plastering, flooring, door and UPVC window installation, and external façade fixing have been completed. Sanitary fittings and external painting work completed and hardscape & landscape works are Completed.

**Villa 75** - Block work, plastering, flooring, door and UPVC window installation, and external façade fixing have been completed. Sanitary fittings and external painting work are also completed. Hardscape & Landscape works are completed.

Actual site photograph



## Sparkling Springs

Off Bannerghatta Main Rd, Bengaluru



Construction Updates

[Overall view](#)

**PHASE 3**

# PHASE 3



**Villa 148** - Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work are completed. sanitary fitting work completed and landscape work completed.

**Villa 149** - Structure completed. Block work & plastering work is completed. Flooring work, UPVC window fixing work completed, external facade work completed, . Hardscape & Landscape works are completed.

**Villa 150** - Structure completed. Block work & plastering work is completed. Flooring work, UPVC window fixing work completed, external facade work completed, . Hardscape & Landscape works are completed.



**Villa 151** - Structure is completed. Block work, plastering, flooring, Door and UPVC window installation have been completed. Painting work and external façade work completed . Hardscape & Landscape works are completed.

**Villa 152** - Structure is completed. Block work, plastering, flooring, Door and UPVC window installation have been completed. Painting work and external façade work completed . Hardscape & Landscape works in progress.

Actual site photograph



**Villa 153** - Block work, plastering, flooring, and UPVC window installation have been completed. Painting and external façade work are in completed . Hardscape & Landscape work in Completed.

**Villa 154** - Block work, plastering, flooring, and UPVC window installation have been completed. Painting and external façade work are completed. sanitary fitting completed . Hardscape & Landscape works are completed.

**Villa 155** - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed. Hardscape & Landscape works are completed.



**Villa 156** - Structure is completed. Block work & plastering is completed, flooring ,putty& water proofing completed. external painting work completed, External façade work Completed. . Hardscape & Landscape works are completed.

**Villa 157** - Structure is completed. Block work & plastering is completed, flooring ,putty& water proofing completed. external painting work completed, External façade work completed. Hardscape works are completed.

**Villa 158** - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed. Hardscape & Landscape works are completed.

Actual site photograph



Villa 162 Villa 161 Villa 160 Villa 159

**Villa 159** - Block work, plastering, flooring, door, and UPVC window installation have been completed. Painting work and external façade work completed . Hardscape & Landscape works are completed..

**Villa 160** - Block work, plastering, flooring, UPVC window installation have been completed. Painting work and external façade work completed. Hardscape & Landscape works are completed.

**Villa 161** - Block work, plastering, flooring, UPVC window installation have been completed. Painting work and external façade work completed. Hardscape work & landscape works are Completed.

**Villa 162** - Block work, plastering, flooring, UPVC window installation have been completed. Painting work and external façade work completed. Hardscape & landscape works completed.

**Villa 163** - Block work, plastering ,flooring, UPVC window installation and putty work are completed. Painting & external façade work completed. Hardscape & Landscape works are completed.

**Villa 164** - Block work, plastering, flooring, and UPVC window installation have been completed. Painting and external façade work Completed. Hardscape & Landscape works are completed.

**Villa 165** - Block work, plastering, flooring, and UPVC window installation have been completed. Painting and external façade work Completed. Hardscape & Landscape works are completed.



Villa 165 Villa 164 Villa 163

Actual site photograph



**Villa 166** - Block work, plastering, flooring, and UPVC window installation have been completed. External façade work is completed, External painting work completed and Sanitary fitting installation work completed. Hardscape & Landscape works are completed.

**Villa 167** - Block work, plastering, flooring, and UPVC window installation have been completed. Painting and external façade work completed. . Hardscape & Landscape works are completed.

**Villa 168** - Block work and plastering, Flooring work are completed. Painting and external façade work are completed. Hardscape work completed.

**Villa 169** - Block work and plastering, Flooring work are completed. Painting and external façade work completed. . Hardscape & Landscape works are completed.

**Villa 170** - Block work, plastering, and flooring have been completed. UPVC window fixing work is also completed. painting and external façade works are completed. Hardscape & Landscape works are completed.

**Villa 171** - Block work & plastering is completed. Flooring, putty work completed. UPVC window fixing, painting work & external façade work completed. Hardscape & Landscape works are completed.

**Villa 172** - Block work, plastering, and flooring have been completed. UPVC window fixing work is also completed. painting and external façade works are completed. Hardscape & Landscape works are completed.

**Villa 173** - Block work & plastering is completed. Flooring, putty work completed. UPVC window fixing, painting work & external façade work completed. Hardscape & Landscape works are completed.

**Villa 174** - Block work, plastering and flooring work completed. UPVC window fixing, painting work & external façade works are completed. Hardscape & Landscape works are completed.



Actual site photograph



**Villa 175** - Block work and plastering are completed. Flooring, Door & UPVC window installation work have also been completed, and external painting completed. ,Façade work completed. Hardscape & Landscape works are completed.

**Villa 176** - Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed. Hardscape & Landscape works are completed.

**Villa 177** - Block work and plastering are completed. Flooring, Door & UPVC window installation work have also been completed, and external painting ,Façade work completed. . Hardscape & Landscape works are completed.

**Villa 178** - Block work, plastering and flooring work completed. window installation and External painting work completed & . Hardscape & Landscape works are completed..

**Villa 179** - Block work, plastering and flooring work completed. window installation, Door installation and painting work completed, external facade work completed. Hardscape & Landscape works are completed.



Actual site photograph



**Villa 180** - Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed. hardscape & landscape works are completed

**Villa 181** - Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed. Hardscape & Landscape works are completed.

**Villa 182** - Block work and plastering are completed. Flooring, Door & UPVC window installation work have also been completed, and external painting ,Façade work completed. . Hardscape & Landscape works are completed.



**Villa 183** - Block work and plastering are completed. Flooring and UPVC Window, Door installation work have also been completed, and external façade& painting work completed. Hardscape & Landscape works are completed.

**Villa 184** - Block work and plastering are completed. Flooring and UPVC Window, Door installation work have also been completed, and external façade& painting work completed. Hardscape & Landscape works are completed.

**Villa 185** - Block work and plastering are completed. Flooring and UPVC Window, Door installation work have also been completed, and external façade& . Hardscape & Landscape works are completed.

Actual site photograph



**Villa 186** - The structure has been completed. Block work, plastering, and flooring have been completed. Painting and UPVC window fixing have also been completed, and external painting work completed. Hardscape & Landscape works are completed.

**Villa 187** - The structure has been completed. Block work ,plastering and flooring work have also been completed. UPVC window installation, and painting work Completed, . Hardscape & Landscape works are completed.



**Villa 188** - Block work, plastering, and flooring have been completed. Painting and UPVC window fixing have also been completed, and external façade completed and external painting work completed. Hardscape & Landscape works are completed.

**Villa 189** - Block work and plastering have been completed. Internal flooring, UPVC window fixing, and external painting work completed and . Hardscape & Landscape works are completed.

Actual site photograph



**Villa 190** - Block work , plastering and flooring work are completed. UPVC window installation work , External façade and painting work completed. Hardscape & Landscape works are completed..

**Villa 191** - Block work and plastering have been completed. Flooring and UPVC window installation work are also completed, external painting work completed. Hardscape & landscape work also completed.



**Villa 192** - Block work and plastering have been completed. Flooring and UPVC window installation work are also completed. external painting work completed. Hardscape & landscape works are completed.

**Villa 193** - Block work , plastering & flooring work completed. painting work, UPVC window & external façade works are Completed. . Hardscape & landscape works are completed.

**Villa 194** - Block work and plastering have been completed. Flooring and UPVC window installation work are also completed, external painting work completed. . Hardscape & Landscape works are completed.

**Villa 195** - Block work , plastering & flooring work completed. painting work, UPVC window and external façade works are completed . Hardscape & Landscape works are completed.

Actual site photograph



**Villa 196** - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed. Hardscape & Landscape work also Completed.

**Villa 197** - The structure has been completed. Block work, plastering, flooring, door and UPVC window fixing have been completed. Painting, external façade work completed and hardscape work completed & Landscape work also completed.



**Villa 198** - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed. Hardscape & Landscape work also Completed.

**Villa 199** - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed. Hardscape & Landscape work also Completed.

Actual site photograph



**Villa 200** - The structure has been completed. Block work, plastering, flooring, door and UPVC window fixing have been completed. Painting and external façade work completed, . Hardscape & Landscape works are completed.

**Villa 201** - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, Painting, external façade work, and sanitary fitting works are completed. Hardscape & Landscape work also Completed.



**Villa 202** - The structure has been completed. Block work ,plastering & flooring work are completed. painting, and UPVC window fixing work completed. Hardscape & landscape works are completed.

**Villa 203** - The structure has been completed. Block work ,plastering & flooring work are completed. painting, and UPVC window fixing work completed, Hardscape & landscape works are completed.

Actual site photograph



**Villa 204** - The structure has been completed. Block work and plastering are completed. Flooring and internal painting work have also been completed. UPVC window and door fixing work and External façade works are completed. Hardscape & Landscape work also Completed.

**Villa 205** - The structure has been completed. Block work and plastering are completed. Flooring ,internal painting , UPVC window fixing work have been completed. External façade work is also completed. Hardscape & Landscape work also Completed.



**Villa 206** - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed. Hardscape & Landscape work also Completed.

**Villa 207** - The structure has been completed. Block work, plastering, and flooring work have been completed. Door fixing, UPVC window installation, internal painting, external façade work, and sanitary fitting work are also completed. Hardscape & Landscape work also Completed.

## Contact us

### Site Office :

#### Sparkling Springs

South Taluk, Kammanahalli Village , Begur Hobli Road,  
Off Bannerghatta Main Rd, Bengaluru, Karnataka – 560076

### Regional Office :

Puravankara Limited. #130/1, Ulsoor Road,  
Bengaluru - 560 042

**Email :** [crm@puravankara.com](mailto:crm@puravankara.com) (Subject line – Project name/ unit number)

**Call Us :** +91 - 80-67724001 / 1 860 208 0000

**Web :** [www.puravankara.com](http://www.puravankara.com)

### OC Number :

JDBL (S)/ADBL/OC/11/2020-21